



URNEX® TRAINING



URN & BREWER CLEANER COFFEE EQUIPMENT CLEANER

INSTRUCTIONS FOR DAILY USE:

1. DISCARD ALL COFFEE FROM VESSEL
2. SPRINKLE URN & BREWER POWDER INTO BREW BASKET.
3. RUN BREW CYCLE INTO SERVER AND HOLD.
4. DISCARD SOLUTION AND REMOVE ANY RESIDUE.
5. RINSE ALL PARTS WITH CLEAN WATER.




1



2



3



4



5

RINSE



URNEX BRANDS, INC

SPECIALIZED EQUIPMENT CLEANERS SINCE 1936

700 EXECUTIVE BLVD ELMSFORD, NY 10523 • TEL 914.963.2042 • FAX 914.963.2145

www.urnex.com